PLANT INFORMATION

PSA Ref #: 00292 Model No: SC550

Plant Name: BLUEBIRD TURF CUTTER SC550

Manufacturer: Crommelins Machinery WA

Manufacturer's Website: www.crommelins.com.au

Web Link for Plant: www.crommelins.com.au Potential noise level in dB: 85 to less than 95

Required hearing protection class: 2

Mandatory Personal Protective Equipment:



Protection







Protection

Protective Clothina

Goggles



RISK ASSESSMENT INFORMATION

Operator Competency: Plant Licence Not Required

Risk Level Potential Hazard(s) Control Measure(s)

Exposure to ultraviolet radiation Medium

if working outdoors.

Explosion or fire from fuel vapours.

Medium

Wear sunscreen, hat, long sleeves and long

 Stop the engine before refuelling. Do not refuel while hot. Avoid spillage of fuel when refuelling. Ensure the fuel cap is properly secured after refuelling. Carry out visual checks for fuel leaks and repair before operation. Keep flammables away from the engine. Warning label on engine. Do not smoke while operating, servicing or refuelling this machine.

Coming into contact with hot

parts of the engine.

Medium/Low

• The muffler is fitted with a heat shield. Let the engine cool down before attempting any maintenance. Avoid contact with hot components. Warning label on engine.

Inhaling exhaust or fuel fumes. Medium/Low Only operate in a well ventilated area. Do not operate in a confined space. Avoid breathing petrol fumes. Avoid skin contact with petrol.

Injury or ill health due to Low exposure to excessive vibration.

• The operator needs to take regular breaks to provide postural relief for safe work practises.

Low Coming into contact with the Keep hands and feet well clear of the cutting cutter blade. blade. Ensure that drive is disengaged and engine is turned off before attempting any adjustments or maintenance. Protective footwear must be worn at all times. Do not use on inclines of more Low Ensure the equipment is operated on a than 20 degrees stable, level surface. Operation across a slope may cause the equipment to be difficult to control. If equipment is tilted while operating, engine seizure may occur due to improper lubrication, even with max. oil level and functioning oil protection system. Fuel spillage may also occur. Hearing damage from excessive Low Hearing protection with a rating of 10db must noise. be worn. Coming into contact with moving Low Belt guard fitted to plant. Do not remove parts. guards or covers. · Protective footwear must be worn at all times.

Customer Identified Hazard(s)

Key Operating Instructions

* When cutting, only operate in "low speed".

Use higher speed only for transport.

Do not attempt to cut in high speed or damage will result.

Before commencing operation mark any submerged obstacles, sprinklers, etc.

To start, turn on the fuel tap by moving the lever to the down position.

Use unleaded fuel only.

Before starting ensure both the drive levers are disengaged.

Ensure the stop switch on the engine is in the ON position.

For cold starting close the choke lever.

Start the engine by pulling the recoil rope with the throttle in low speed position.

As the engine warms up return the choke lever to the open position.

Set the depth adjuster knob to the desired depth, increase the speed, engage the cutter lever and let the cutter cut under the turf. It may be easier to dig a start hole for the cutter blade.

The speed should be set to a comfortable walking pace.

To commence operation engage the drive lever to move forward.

To stop the machine disengage both the cutter and the drive lever, return the throttle to the idle position, turn the engine stop switch OFF and turn off the fuel tap.

Please refer to the User Guide and Operator's Manual for Operating Instructions

The Safety Information on this assessment has been developed for the Hire and Rental Industry to assist in the safe operation of this equipment.

This information contains general information only and should not be relied upon as a substitute for professional advice, which the user should seek before operating.

Once printed this is an uncontrolled copy.